

J. Jeffrey Huber Daily Report

River Activities – Electron Crew heading to the area of Ledout Creek to find Astro-Turf locate by PTI.

Construction Activities – Bank Stabilization & Road cleanup leading down to the river at the intake area.

JH – 0700 Electron Crew onsite to deal with bank stabilization and road clean up.

JH – 0800 Electron Crew working on the South Bank doing bank stabilization. Electron crew is using boulders and concrete risers along the South bank just West of the Tainter Gate bridge. No communication with the river.

JH – Electron Crew led by Corey A. went to the area of Ledout Creek to attempt to find Astro-Turf found by PTI. None Found

JH – 1830 River appears to be naturally turbid coming from upstream. Fish ladder appears to be functional and in good operating order.

JH – Electron crew will continue to clean up roads and stabilize the river bank along the access road going down to the flume. This construction is being done around the tainter gate.

Sincerely,

J. Jeffrey Huber Encore Environmental



Independent Compliance Monitor on Behalf of Pierce County Electron Hydro